



1/4-20 Socket Head Cap Screws with Jamb Nuts - four (4) locations




Section A-A



Section B-B

1/4-20 Dog-Point Hex-Socket Set Screws, three (3) locations



Section C-C